

2006 3 Series

VIN Code:

WBAVU11010KW90678

Model:

3 Series 318D UL (EUR)

Steering:

Left Hand Drive

Power:

90kw / 122hp

Colour:

SCHWARZ 2 (668)

Year:

2006-05-29

Body Type:

TOUR

Engine:

M47T2 2.00 cm3

Transmission:

Manual

Interior:

STOFF FLUIDANTHRAZIT (ALAT)

ODOMETER CHECK

St	tatus	Event Date	Event Location	Odometer Reading	Event Detail
		2010-03-08	Kortrijk	159,000 km	Inspection
		2009-09-15	Inspection Station	155,000 km	Inspection
		2009-07-27	Berlin	150,000 km	Inspection
	3	2008-09-08	Inspection Station	85,000 km	Inspection
		2008-08-07	Inspection Station	119,000 km	Inspection
		2008-04-17	Inspection Station	106,000 km	Inspection
		2008-02-20	Inspection Station	92,000 km	Inspection
		2007-12-28	Inspection Station	86,000 km	Inspection
		2007-11-22	Inspection Station	84,000 km	Inspection
		2007-08-08	Inspection Station	70,000 km	Inspection
		2007-06-18	Inspection Station	60,000 km	Inspection
		2007-01-10	Inspection Station	35,000 km	Inspection
		2006-10-23	Inspection Station	20,000 km	Inspection
	②	2006-06-09	Inspection Station	0,000 km	Inspection

ACCIDENT CHECK

No records found.

STOLEN VEHICLE DATABASE

No records found.

EQUIPMENT LIST

SICAA - SELECTION OF COP RELEVANT VEHICLES

S320A - DELETED MODEL LETTERING

S423A - FLOOR MATS VELOURS

S441A - SMOKER PACKAGE

S507A - PARK DISTANCE CONTROL PDC REAR

S534A - AUTOMATIC AIR CONDITIONING

L801A - NATIONAL VERSION GERMANY

S879A - ONBOARD VEHICLE LITERATURE GERMAN

S4AGA - INTERIOR TRIM FINISHERS TITANIUM MATT

\$851A - LANGUAGE VERSION GERMAN

S200A - DIESEL PARTICLE FILTER

S386A - ROOF RAILING

S428A - WARNING TRIANGLE AND FIRST AID KIT

S481A - SPORTS SEAT

S520A - FOG LIGHTS

P735A - BASIC PACKAGE

S863A - RETAILER DIRECTORY EUROPE

S8SPA - CONTROL UNIT COP

S548A - KILOMETERCALIBRATED SPEEDOMETER

www.auto-records.com at 01-07-2017